

George C. Larson, vice PRESIDENT c: 403-862-9432 d: 403-294-7182 glarson@barclaystreet.com


Manish Adiani, VICE PRESIDENT c: 403-975-0694 d: 403-294-7181 adianim@barclaystreet.com








- » Fully leased with reversionary upside.
- » Tenants include IGA and Bank of Nova Scotia.
- » Limited area competition.
- » Additional development land included.
- » Well-maintained and aesthetically pleasing.
- » Largely national retail income available under \$200.00 per sq. ft.





PROPERTY INFORMATION

MUNICIPAL ADDRESS:

11001 20th Avenue, Blairmore, AB

LEGAL: Plan 8188 G.P.; Parcel C.

Excepting thereout all mines and minerals Containing 3.48 hectares (8.60 acres) more or less

ZONING: C-3: Comprehensive Commercial

BUILDING AREA: 56,938 sq. ft. (leasable)

LAND AREA:

8.60 acres including approximately 3.37 acres of undeveloped land

YEAR BUILT/RENOVATED: 1976/1999

TENANCY:

Leased 100%. Tenants:











H&R BLOCK

BLAIRMORE SELF STORAGE

5 RIVER PIZZA

MEDICAL CLINIC

PHARMACY

FINANCING: Treat as Clear Title

PRICE: Please contact brokers





ROOF

The property consists of three separate roofing systems. The oldest system, which covers the space currently occupied by IGA, which was replaced approximately 7 years ago, consists of a built-up asphalt membrane over top of rigid fiberglass insulation. The membrane is topped with silver paint rather than gravel due to the frequent high winds in the area.

The second roofing system which covers the NE section of the mall, directly north of the IGA, is finished with a 'Proseal' polyester reinforced single ply membrane over rigid insulation. This membrane covers approximately 36,000 sq. ft. and was done in 2020.

The third roofing system, which covers the remaining roof structure to the west of the IGA, consists of a torch-applied modified bituminous membrane system, with granular surface finish over existing rigid fiberglass insulation was replaced in 2000.

Store front arcade canopies of pre-finished corrugated metal cover exterior walkways to the west and south.

PARKING LOT

The lot was resurfaced in 2011 and the parking lot lights were all changed to LED.

MECHANICAL/ HVAC SYSTEMS

PLUMBING:

Main cold water service runs to the shopping centre, providing potable water for human consumption, as well as supplying the water to the sprinkler system for fire protection.

STORM SYSTEMS:

The centre's roof contains storm drains, and rain water is collected and distributed via storm piping to the perimeter of the building where it is dispersed onto a paved lot.

HVAC:

Each tenant bay is serviced by an individual packaged gas fired, heating/electric cooling roof top unit. The units are inspected annually and repaired or replaced as required. A large percentage have been replaced.

















